

Mr. Mike Bradley Utah Department of Oil, Gas & Mining 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

Mr. Paul Baker Utah Department of Oil, Gas & Mining 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

Mr. Wayne Western Utah Department of Oil, Gas & Mining 1594 West North Temple, Suite 1210 PO Box 145801 Salt Lake City, Utah 84114-5801

Re: Minerals Inspection Report October 25/2013. Lisbon Valley Mining Co LLC, 920 South County Road 313, La Sal, Utah, 84530. DOGM Permit M/037/088

The Lisbon Valley Mining Co LLC [LVMC (Operator)] respectfully submits this response to the DOGM Minerals Inspection Report October 25, 2013 and wishes to thank the agencies for their continued guidance and support.

A comment is warranted with regard to the present degree of rilling and gullying at LVMC. In mid-September LVMC was subjected to an unusual storm event that caused damage to County Road 313 at the Three Step Hill area, moved large piles of rip/rap down the county road drainages and caused rilling and gullying on Dump C. Moments of heavy precipitation over short periods defined the unusual nature of this storm event. Images are included to compare the County Road damage with the gullying at LVMC

November 11, 2013

RECEIVED NOV 1 5 2013

DIV.OFOIL.GAS&MINING

Moving forward, LVMC remains committed to implementation of appropriately sized rip/rap on the C dump and in other drainage systems in accordance with DOGM's comments and recommendations. We will be installing rip/rap in gullies and drainage channels before year's end according to opportunity. In addition we will immediately implement a reduction of dozer basin size.

Sincerely,

Lantz M Indergard Environmental Manager Lisbon Valley Mining Co LLC (435) 686 9950 #107

Lindergard@lisbonmine.com

Attachment Late Summer 2013 Photos























